## **Edging & Mounting Guidelines for GKB Lenses**

Step 1	Blocking
а	Scanning of Barcode on the Job
b	Check the screen for correct values
С	Alling the lens in the blocking machine as per the Lens markings
d	Put the Blocking Pad & Chuck in the machine
е	Press blocking button to block.
Step 2	Edging
а	Scanning of Barcode from the Job
b	To check the shape, it's as per the job Thicket
С	Insert the lens in the edging machine.
d	Machine will edge the lens automatically and stop when finish
Step 3	Drilling
а	Select the manufacturers frame details through software (OptiDrill)
b	Select the manufacturers frame details through software (OptiDrill)  Mount the lens on the drill machine check in right & left position start the drill
С	check in right & left position
d	start the drill
е	Machine will complete the process automatically
Step 4	Mounting
	Mounting of lenses is mostly done by hand by an experience technician
	Make sure that you are using all the safety measures before starting job

## **Contact us**

GKB Optic Technologies Pvt Ltd.129G, 19,20 & 21, Noida Special Economic Zone, Noida - 201305 India Ph: +91-120 4540020, 4540021